ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli
Street ID	**Street Name**	**Significant Landmark**
W0607	NA	handiguda road at bhadrappa layout
Segment No.	**Total Length (m)**	
8/S-W0607/S103652	112.37	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	112.37	77.573253	13.048755	77.572633	13.049569	W0609	SDW

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Providing cc road at Kodigehalli connection road at Kodigehalli village and construction if culvert at junction of 1st main and handiguda road at bhad	1300000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Providing cc road at Kodigehalli connection road at Kodigehalli village and construction if culvert at junction of 1st main and handiguda road at bhadrappa layout main road in Ward no 8 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone	008-15-000021
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/WO/292/2014-15	05/02/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
05/02/2015	04/02/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
P VIJAYA BABU		0.00
Phone No.	**E-Mail ID**	

9845025446

Field Inspection Details

Number of Trees	Any Other Information	Name
0		SRINIVASA MURTHY
Date of Inspection	**Remarks**	
15/09/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	15/09/2016	15/10/2016	COMPLETED
SE	VASU K M	15/09/2016	15/10/2016	COMPLETED
EE	YARAPPA REDDY	15/09/2016	15/10/2016	COMPLETED
AEE	RAJANIKANTH	15/09/2016	15/10/2016	COMPLETED
AE	SRINIVAS MURTHY	15/09/2016	15/10/2016	COMPLETED
AE	SRINIVAS MURTHY	15/09/2016	15/10/2016	COMPLETED